
Square holes in straight lines




w = hole widthth = pitch horizontaltv = pitch vertical


In direction of perforation it is possible to realise unperforated strips or areas, depending on the perforation pattern.

Please do not hesitate to ask for technical support in an early product development phase.


It will be your advantage!




Nr. 4014 (Qg 1,1 - 1,6)	mm
hole width	1,1
pitch horizontal	1,6
pitch vertical	1,6
opening	47 %




Nr. 4032 (Qg 3,0 - 4,0)	mm
hole width	3,0
pitch horizontal	4,0
pitch vertical	4,0
opening	56 %




Nr. 4077 (Qg 2,0 - 3,0)	mm
hole width	2,0
pitch horizontal	3,0
pitch vertical	3,0
opening	44 %




Nr. 4253 (Qg 5,0 - 6,0)	mm
hole width	5,0
pitch horizontal	6,0
pitch vertical	6,0
opening	69 %



Nr. 4288 (Qg 1,5 - 2,2)	mm
hole width	1,5
pitch horizontal	2,2
pitch vertical	2,2
opening	46 %



Nr. 4319 (Qg 1,2 - 1,7) hole width pitch horizontal	mm 1,2 1,7
pitch vertical opening	1,7 50 %



Nr. 4333 (Qg 2,0 - 2,5)	mm
hole width	2,0
pitch horizontal	2,5
pitch vertical	2,5
opening	64 %