



Rectangular holes in staggered lines




w = hole width
 = breadth x height
th = pitch horizontal
tv = pitch vertical

In direction of perforation it is possible to realise unperforated strips or areas, depending on the perforation pattern.


Please do not hesitate to ask for technical support in an early product development phase. It will be your advantage!




Nr. 1490 mm
 hole width b x h 4,0 x 1,0
 pitch horizontal 5,4
 pitch vertical 2,25+2,25
 opening 33 %




Nr. 1491 mm
 hole width b x h 5,0 x 0,8
 pitch horizontal 8,0
 pitch vertical 2,0+2,0
 opening 25 %



Nr. 4183 mm
 hole width b x h 5,0 x 0,8
 pitch horizontal 5,9
 pitch vertical 2,0+2,0
 opening 34 %



Nr. 4305 mm
 hole width b x h 0,85 x 5,0
 pitch horizontal 2,0+2,0
 pitch vertical 8,0
 opening 26,5 %



Nr. 4349 mm
 hole width b x h 1,2 x 2,4
 pitch horizontal 1,8+1,8
 pitch vertical 6,0
 opening 26,7 %